



"I'VE GOT A SMILE WHENEVER
I SEE HER NOW."

BMW COSMETIC REPAIRS.

SAY GOODBYE TO SCRATCHED RIMS.

BMW ALLOY WHEEL REPAIR.

Rim damage can be superficial or require extensive repair. Our trained and qualified BMW Service Technicians can restore your rim with high quality results through innovative solutions or recommend a wheel replacement for your utmost safety. You can also express your style on the road with rim spray painting services at our Sime Darby Performance Centre at 303 Alexandra Road.

BMW ALLOY RIM REPAIR/ RESTORATION (PER RIM)	WHEEL BALANCING	PRICE PER RIM [^] (WITHOUT GST)
Alloy Rim – Spot Repair	Yes	\$80
Alloy Rim – Spray Paint (same or change colour)	Yes	\$100
Alloy Rim – Spray Paint (matte colour)	Yes	\$120
Machined Rim – Spot Repair	Yes	\$150

To make an appointment, please approach any BMW Customer Service Advisor or call 1800-2255-269 today.

ENJOY DENT-FREE DRIVING PLEASURE.

BMW DENT REPAIR.

Cosmetic repairs are performed with high level of quality and precision at all Authorised BMW Service Centres. Combined with the use of Original BMW Parts, we ensure that your BMW retains its perfect appearance and value. So, no matter the nick or bump weathered from the rush of driving, get to have all your dents smoothened out.

After all, it's about making sure you experience the joy of having your BMW in showroom condition once more.

HOW TO ESTIMATE YOUR REPAIR COST?

Finding a dent on your BMW can shatter your peace of mind, causing you unnecessary worry about the cost of repair. Learn how you can use everyday items to measure the size of the dent and get an estimate of the cost.



STEP 1

Take a 20-cent coin or a golf ball



STEP 2

Place it in front of the dent



STEP 3

Check against the table below to get your cost estimate

PRICING TABLE FOR SIDE PANELS: DOORS AND FENDERS

DENT CLASS	SIZE	GUIDELINE	PRICE*
A	≤ 21mm	20 cents coin size or smaller	From \$70 Subsequent dent at \$27
B	21.1mm – 45mm	Between size of 20 cents coin and Golf ball	From \$81 Subsequent dent at \$33
E	45.1mm – 65mm	Golf ball size or bigger	\$118 and above

Alternatively, get to enjoy a full panel dent repair from just \$400.

PRICING TABLE FOR TOP PANELS: ROOF, BONNET AND BOOTLID

DENT CLASS	SIZE	GUIDELINE	PRICE*
A	≤ 21mm	20 cents coin size or smaller	From \$81 Subsequent dent at \$33
B	21.1mm – 45mm	Between size of 20 cents coin and Golf ball	From \$91 Subsequent dent at \$38
E	45.1mm – 65mm	Golf ball size or bigger	\$134 and above

Alternatively, get to enjoy a full panel dent repair from just \$400.

Visit Performance Motors or call 1800-2255-269 to find out more.

MAKE AN APPOINTMENT WITH OUR SERVICE CENTRES TODAY.

BMW SERVICE CENTRES

Sime Darby Performance Centre

303 Alexandra Road

East Coast Centre

280 Kampong Arang Road

Contactless Centre

(by appointment only)

1 Ubi Road 4

APPROVED BMW BODYSHOP

Sime Darby Performance Centre

303 Alexandra Road

pml-bmw.com.sg

PERFORMANCE MOTORS LIMITED

1800-2255-269 (1800-CALL-BMW)

Monday – Friday
8.00am – 6.30pm

Saturday
8.00am – 12.00pm

Performance Motors Accident Response Team (24 hours):

1800-2255-269
Select '1' once dialled in.

[^]Alloy Wheel Repair services are only available at the Approved BMW Bodyshop – Sime Darby Performance Centre, 303 Alexandra Road. Price is inclusive of removal or installation of wheel(s) if necessary, wheel balancing and 2K Paint Material. Colour tone may differ for spot repair on minor edge machining rim. Repair job(s) is subjected to assessment and evaluation by Customer Service Advisors. The duration of work required is dependent on the nature and severity of damage, wheel type, material, and surface finish. All workmanship on repair surface area includes a 6-month warranty. All prices quoted are in Singapore Dollars and are exclusive of GST. Prices are subject to change without prior notice.

*Repair jobs and costs are subjected to assessment and evaluation by Customer Service Advisors. The duration of work required is dependent on the nature and severity of damage. The above-mentioned repair services do not cover all parts of the vehicle body. Prices are subject to change without prior notice.